

### Annex III

#### List of inspection activities for which accreditation has been terminated

(Notification letter No.: HKIAS032-11; Effective Date of Termination: 14 November 2024)

#### Environmental Pioneers & Solutions Limited

大成環境科技拓展有限公司

Flat A, 8/F, Chai Wan Industrial Centre, 20 Lee Chung Street, Chai Wan, Hong Kong

香港柴灣利眾街 20 號柴灣中心工業大廈 8 樓 A 座

<b>Indoor Air Quality Inspection 室內空氣質素檢驗</b>		
<b>ITEM INSPECTED</b> 檢驗項目	<b>SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED</b> 特定檢驗特性或特徵	<b>SPECIFIC INSPECTION METHOD OR STANDARD</b> 特定檢驗方法或標準
<b>Accreditation of the following inspection activities has been terminated</b>		
Indoor Air Quality Inspection	On-site measurement of : - Temperature  - Relative Humidity  - Air Movement  - Carbon Dioxide  - Carbon Monoxide  - Respirable Suspended Particulate  - Ozone  - Total Volatile Organic Compound  - Radon  On-site sampling of : - Nitrogen Dioxide  - Formaldehyde  - Airborne Bacteria	A Guide on Indoor Air Quality Certification Scheme for Offices and Public Places, The Government of the HKSAR, Indoor Air Quality Management Group, September 2003  Annex 3 (a), as documented in Method ISP03 (Temperature sensor, thermistor)  Annex 3 (a), as documented in ISP04 (Humidity sensor capacitive measurement principle)  Annex 3 (a), as documented in ISP05 (Hot wire velocity probe)  Annex 3 (b), as documented in ISP06 (Non-dispersive infrared NDIR)  Annex 3 (b), as documented in ISP07 (Electrochemical sensor)  Annex 3 (g), as documented in ISP11 (Light scattering laser diode)  Annex 3 (f), as documented in ISP10 (Gas sensitive semiconductor)  Annex 3 (h), as documented in ISP08 (Photo-ionization sensor)  Annex 3 (c), as documented in ISP09 (Electrostatic collection of alpha-emitters with spectral analysis)  Annex 3 (e), as documented in ISP13 (Passive sampler)  Annex 3 (d), as documented in ISP12 (Passive sampler)  Annex 3 (i), as documented in ISP14 (Single stage impactor)

### Annex III

#### List of inspection activities for which accreditation has been terminated

(Notification letter No.: HKIAS032-11; Effective Date of Termination: 14 November 2024)

#### Environmental Pioneers & Solutions Limited

大成環境科技拓展有限公司

Flat A, 8/F, Chai Wan Industrial Centre, 20 Lee Chung Street, Chai Wan, Hong Kong

香港柴灣利眾街 20 號柴灣中心工業大廈 8 樓 A 座

<b>Indoor Air Quality Inspection 室內空氣質素檢驗</b>		
<b>ITEM INSPECTED</b> 檢驗項目	<b>SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED</b> 特定檢驗特性或特徵	<b>SPECIFIC INSPECTION METHOD OR STANDARD</b> 特定檢驗方法或標準
<b>Accreditation of the following inspection activities has been terminated</b>		
Indoor Air Quality Inspection (Cont'd)	Walkthrough Inspection  IAQ Compliance Assessment	A Guide on Indoor Air Quality Certification Scheme for Offices and Public Places, The Government of the HKSAR, Indoor Air Quality Management Group, September 2003  Clause 11  Clause 13 to Clause 28